

Figure 2

3/7




Figure 3




Figure 4a




Figure 4b

120

30

5/7

125

124

126

30'

121

123

Figure 5a

30

Figure 5b

125

P

r

Figure 5a is a schematic diagram of a mechanical assembly. The assembly includes a base 120, a frame 122, and a central shaft 121. The shaft 121 is supported by bearings 123 and 124. A component 125 is mounted on the shaft 121. A component 126 is also shown. A dashed line 30 indicates a reference line. A component 30' is also shown. Figure 5b is a circular diagram showing a point P and a radius r.

Figure 6a




Figure 6b

